

Illinois Commerce Commission**Pipeline Safety****Pipeline Safety Report****Inspection #: 2015-P-00105**

| | |
|---|----------------------|
| Operator: DYNEGY KENDALL ENERGY, LLC | Operator ID#: 32210 |
| Exit Meeting Contact: (Not Applicable) | Total Man Days: 0 |
| Pipeline Safety Representative(s): Jim Watts | |
| Company Representative to Receive Report: Tod Benninghoff | Emailed Date: |
| Company Representative's Email Address: todd.benninghoff@dynegy.com | 05/11/2015 |

Inspection Summary

| Inspection Type | Location | ICC Analyst | Inspection Unit(s) | Man Day(s) | Inspection Date(s) | Contact(s) |
|---|------------|-------------|--------------------------|------------|--------------------|------------|
| Standard Inspection Annual Report Review | ICC Office | Jim Watts | Dynegy Kendall Energy | 0 | 5/5/2015 | |

Statement of Activities

On May 5, 2015, Staff conducted a review of the 2014 Annual DOT Transmission Report submitted to the ICC by Dynegy Kendall Energy, LLC. The review is required to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590. Staff observed no issues with the data reported in the 2014 annual report submitted for review.

Exit Statement**INSPECTION FINDINGS****Standard Inspection Annual Report Review****Issues(s) Found:**

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS**Issue(s) Corrected:**

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

**Illinois Commerce Commission
Pipeline Safety
Pipeline Safety Report**

Inspection #: 2015-P-00105

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]